Craf	Task / Skill	(Task No.) Task Description	Associated Training	Training
t				Hours
Μ	Adjust and replace belt wipers / cleaners	Limited work scope, assists with housekeeping concerns	TLO	
М	Lubricate bearings		TLO	
Μ	Replace / clean strainers and filters	[TRSESM-07.003] Clean/Replace Filtration Element (Cloth, Steel, Mesh,	Filters/Strainers	
		fiber)		2
М	Add and/or change oil in equipment	[TRSESM-08.053] Drain and Refill Equipment Lubricating Oil	Lubrication	
E	Reset breaker overloads	Reset once only, arc flash training required to open panel	Breakers/Switchgear for Ops	4
E	Use a Handheld Strobe Light Tachometer	[TRSEL-03.009] Use a Hand Held Strobe Light Tachometer	Test Instruments	
E	Repair / adjust limit switches (non MOV)	[TRSEL-08.032] Functionally Test and Adjust Limit Switches	TLO	TBD
E	Grease motors / equipment	[TRSESM-08.053] Drain and Refill Equipment Lubricating Oil	Lubrication	
E	Add and/or change oil in motors	[TRSESM-08.053] Drain and Refill Equipment Lubricating Oil	Lubrication	
E	Replace motor filters	[TRSEL-10.002] Clean and/or Replace Filtration Element (Cloth, Steel,	Filters/Strainers	
		Mesh, Fiber) - Electrician		
E	Perform pull cord preventive maintenance	Perform PM checks and documentation, not repair/replace	TLO	
E	Perform tilt switch preventive maintenance	Include minor corrective, plug and play probes	TLO	
E	Replace all types of light bulbs (including indicator lights)		TLO	
E	Perform belt scale calibration		TLO	
Е	Perform metal detector preventive maintenance		TLO	
HVAC	Replace HVAC filters		TLO	
HVAC	Replace ventilation filters		TLO	